

Ĩ								
The "X" in the part number refers to the Quality Level	Dimensions are in inc	COAST/ACM						
(C, B, E, or S), see Quality Assurance Provisions	tolerances are: Fractions Decima .XX = ±0.0	13	TITLE Inductor					
above.	±1/64 .XXX=±0	+1/2°	FSCM		DWG. NC		0001	REV.
	DRAWN BY	DATE	2255	8		32	2339X	
DO NOT SCALE DRAWING	Jim Allen	4/9/03	SCALE: none	MA	X. WT.:	4 grams	SHEET	1 OF 1